


Copyright 1897
Machinery

435
270
R

(4 SHEETS)
SHEET 18

Fig. 1.



838
97

Fig. 2.





Fig. 3.



rising & falling movement
in part of bar B through crank
connection. 3

Given three distinct steps in its
forward movement
1. Advances font and
required position on grid for
dipping
2. After slight retrograde
movement and dial
bring font and a
little short of grid
and remaining there
during descent
3. Now close
font and
W.

Fig 4

